

# Service Parts Diagrams

For Model: KAPP-IQ55

## **Service Parts Diagrams Revision History**

### Revision 1 - June, 2015

New document

### Revision 2 - February, 2016

- Remove UGK-KAPPIQ-AM30
- Add FRU-KAPPIQ-AM30, 1027962 and 93-063

### Revision 3 - March, 2017

- Remove 1025924, 1025925 and FRU-KAPPIQ-AM30
- Add 93-00708-20, 93-00654-20, 1018969, 1018970, 1018971, 1018972, 1025597, 1025603, 1025826, 1028647, 1028646, 1028204 and FRU-KAPPIQ-AM30-ENT

### **Standard Warranty Terms**

Base product: Two-year limited equipment warranty

First Customer Ship: June, 2015



Calgary, AB T2L 1Y1
CANADA

Support +1.403.228.5940 or Toll Free 1.866.518.6791 (Canada/U.S.)

Support Fax +1.403.806.1256

www.smarttech.com/contactserviceparts www.smarttech.com




# **Service Parts Diagrams for the KAPP-IQ55**

Identifying Your Product Using the Serial Number	′
Ordering Parts	′
VADD IOSS David	

## **Identifying Your Product Using the Serial Number**

To make sure that you have the correct service parts diagrams, you must verify the serial number of your KAPP-IQ55. The serial number of the flat panel display will be located on the right underside of the bottom bezel. The serial number of the AM30 will be located on the top of the appliance. An example of the serial number format is shown below.



# **Ordering Parts**

#### **Customers**

To order any of the parts in these service parts diagrams, contact your local reseller. To find a reseller near you, visit www.smarttech.com\where.


### **Dealers and Distributors**

For specific technical and pricing enquiries in regards to these diagrams please contact our service parts department. Pricing is also available on-line via the SOURCE website (source.smarttech.com).

Web Form: www.smarttech.com/contactserviceparts

Phone: 1.888.42.SMART International: +1.403.245.0333

# **KAPP-IQ55 Parts**



Item	Part No.	Qty	Description
1	1028647	1	Replacement Pen for SPNL-6000 Series and SBID8000-G5 Series - Red
2	1028646	1	Replacement Pen for SPNL-6000 Series and SBID8000-G5 Series - Black
3	FRU-KAPPIQ-AM30-ENT	1	AM30 field replaceable unit for enterprise customers  NOTE: Includes AM30 and item 4.  NOTE: This is only to replace AM30's that have a part number of 1028765 or 1025159.
4	1027962	1	Antenna
5	1022063	1	Cable, power, North America, 8' (2.4 m)
5	93-055	1	Cable, power, United Kingdom, 8' (2.4 m)
5	93-056	1	Cable, power, Autstralia, 8' (2.4 m)
5	93-054	1	Cable, power, Europe, 8' (2.4 m)
5	93-00708-20	1	Cable, power, China, 8' (2.4 m)
5	93-00654-20	1	Cable, power, Japan, 8' (2.4 m)
5	93-063	1	Cable, power, South Africa, 8' (2.4 m)
5	1018969	1	Cable, power, Singapore, 14' 9" (4.5 m)
5	1018970	1	Cable, power, India, 14' 9" (4.5 m)
5	1018971	1	Cable, power, Saudi Arabia, 14' 9" (4.5 m)
5	1018972	1	Cable, power, Brazil, 14' 9" (4.5 m)
5	1025597	1	Cable, power, Argentina, 14' 9" (4.5 m)
5	1025603	1	Cable, power, Chile and Italy, 14' 9" (4.5 m)
6	1028204	1	Assembly, input/output board, KAPP-IQ55  NOTE: Comes attached to the KAPP-IQ55.
Not shown	1025826	1	Kit, packaging, KAPP-IQ55