

TECHNICAL BULLETIN

November 14, 2006

Computers With Intel® D102 Motherboards Won't Start When a SMART Board™ 600 Series Interactive Whiteboard is Connected

Issue

If you connect a SMART Board 600 series interactive whiteboard to the USB receptacle of a computer that has an Intel D102 motherboard, the computer stops responding during the startup process. When you disconnect the interactive whiteboard, the computer starts normally.

Solution

This is a known issue with the D102 motherboard's BIOS firmware. Contact your computer's reseller to determine if a BIOS firmware update is available from Intel Corporation.

SMART Technologies Inc.

1207 – 11 Avenue SW, Suite 300
Calgary, AB T3C 0M5
CANADA
Support +1.403.228.5940 or Toll Free 1.866.518.6791 (Canada/U.S.)
Support Fax +1.403.806.1256
support@smarttech.com www.smarttech.com

