Important information for your interactive display overlay

WARNING

- Failure to follow the installation instructions shipped with your SMART product could result in personal injury and damage to the product which may not be covered by your warranty.
- Ensure that any cables extending across the floor to your SMART product are properly bundled and marked to avoid a trip hazard.
- You must connect the USB cable that came with your interactive display overlay to a
 computer that has a USB compliant interface and that bears the USB logo. In addition,
 the USB source computer must be compliant with CSA/UL/EN 60950 and bear the CE
 mark and CSA and/or UL Mark(s) for CSA/UL 60950. This is for operating safety and to
 avoid damage to the interactive display overlay which may not be covered by your
 warranty.
- To reduce the risk of fire or electric shock, do not expose the SMART product to rain or moisture.

www.smarttech.com/support | www.smarttech.com/contactsupport Support +1.403.228.5940 or Toll Free 1.866.518.6791 (U.S./Canada)

© 2011 SMART Technologies ULC. All rights reserved. The SMART logo, smarttech, and all SMART taglines are trademarks or registered trademarks of SMART Technologies ULC in the U.S. and/or other countries. All third-party product and company names may be trademarks of their respective owners. Contents are subject to change without notice. 06/2011.